

# SI-BONE Complaint - Revision - Post Market - Feedback Reporting

Use this form to submit information about a complaint related to an SI-BONE product to Quality Affairs. Contact QA@si-bone.com if you have any questions.

Select the type of problem you are reporting

Problem with individual device or individual patient

## General Feedback about SI-BONE Product

This is only for non complaint information. Examples: surgeon suggestions, meeting discussions, etc. For complaints, go back and select "Problem..."

## Contact Info

Use this to record your attempts to contact and gather information from the surgeon.

Kristi Rhodes Your name

Your email krhodes@si-bone.com

Your phone number (504) 813-7475

**Christopher Cenac** Surgeon's name

Contact #1: How did you attempt to

contact the surgeon?

Text

Was this attempt successful?

Yes

# **Complaint Overview**

Enter information about surgery that resulted in a problem with any SI-BONE implant, instrument or accessory (e.g., drill bit, pin).

Date you first heard of problem with SI-BONE product.

Friday, December 9, 2022

If problem occurred during placement Tuesday, November 15, 2022 of an SI-BONE device, enter date placed (initial procedure), not date of revision surgery.

Which device(s) was/were affected?

iFuse-3D

## Part number(s), if available

7060M-90

#### Lot number(s), if available

9048541

# **Product Complaint or Adverse Event?**

Decide what type of report you are submitting.

Use this form to submit information about a complaint related to an SI-BONE product to Quality Affairs. Contact <a href="QA@si-bone.com">QA@si-bone.com</a> if you have any questions.

What is the nature of the problem you are reporting?

Product complaint that caused or may have caused an adverse event or revision procedure

# **Product Complaint Without Adverse Event**

Use this form to report an SI-BONE product problem that was NOT associated with a patient adverse event.

Examples include:

- Damaged instrument
- Broken pin
- Bent pin
- · Pin advancement but no patient injury
- Problem with packaging

If a damaged part injured a patient, go back and click on "Product complaint that caused or may have caused an adverse event."

# **Select Adverse Event Type**

Select from the choices below. Your choice guides which section to complete.

If the first 3 do not apply, select "Other".

If a product problem occurred that did NOT cause a patient problem, go back and complete the "Product Complaint Without Adverse Event" section.

What problem did patient have?

Pain did not improve or recurred

## **Symptomatic Implant Malposition Form**

Use this form if patient experienced symptomatic implant malposition resulting in nerve irritation.

(Information should be from SI-BONE staff who attended initial surgery)

The surgeon completed all steps in the IFU, including:

- Patient setup (table, spine neutral position, prone or supine position)
- Inspection of instruments and implants prior to use
- Proper views (lateral, inlet and outlet) obtained during use of instruments and placement of implants that clearly showed recommended anatomic landmarks
- Appropriate implant starting position
- (If performed) proper use of neuromonitoring guide pin and equipment
   Use of length gauge for implant length selection
- Were standard wound closure techniques used?

For above question, be specific and include all steps of the revision surgery and any complications.



- Was the implant adjusted, removed or added?
- Were the explant holes filled with bone graft?
- Were osteotomes and the/or the removal adapter used?
- Was any non-iFuse hardware installed?

# **Pain Did Not Improve or Recurred**

Use this form if pain did not improve OR pain improved but then recurred

Best description of time course of pain recurrence:

How long was SI joint pain relieved before recurrence of pain symptoms?

Compared to preoperative level, pain

Pain got better but then recurred

2 weeks

Worse

now is

CT imaging to evaluate pain

He felt the implant was right on the foramen

recurrence shows:

CT findings (check all that apply)

CT was done and doctor has shared findings with me

Is doctor willing to share CT images with SI-BONE?

CT done, doctor NOT willing to share

Imaging type used during initial surgery

C-arm/fluoro only

Was initial surgery attended by SI-

Yes

Name of SI-BONE staff member attending initial surgery

**BONE staff member?** 

Kristi Rhodes

(Information should be from SI-BONE staff who attended initial surgery)

The surgeon completed all steps in the IFU, including:

- Patient setup (table, spine neutral position, prone or supine position)
- Inspection of instruments and implants prior to use
- Proper views (lateral, inlet and outlet) obtained during use of instruments and placement of implants that clearly showed recommended anatomic landmarks
- Appropriate implant starting position
- (If performed) proper use of neuromonitoring guide pin and equipment
   Use of length gauge for implant length selection
- Were standard wound closure techniques used?

See summary of IFU steps. Did surgeon complete all steps as shown above?

Yes, all steps were completed accurately

#### Enter details about skipped or incorrectly executed step.

Implant did not look near the foramen under Fluoro. He feels like the implant must have moved.

Were any additional causes of low back / pelvic pain evident or discovered during workup?

No other cause determined or suspected

Were any SI-BONE implants removed or adjusted as a result of this problem?

Yes, one or more implants were adjusted or removed

## **Describe revision procedure.**

He removed the top implant and went in with a shorter 7.5 implant.

## **Surgical Wound Problem**

Use this form if patient developed postoperative surgical wound problem (infection, dehiscence).

## **Other Problem**

Use this section ONLY if the patient problem is **NOT**:

- Implant malposition causing nerve irritation
- Pain did not improve or recurred
- Surgical wound problem

# **Potential Warranty Case**

Please help evaluate whether this case could qualify for SI-BONE's warranty policy.

Did patient's situation meet all of the following?

Did patient undergo a revision procedure that met all of the following:

- 1. The initial procedure involved placement of 3 SI-BONE implants on the affected side
- 2. The revision procedure:
  - Was completed within 1 year of the initial procedure
  - Was completed at the same hospital or within the same hospital system as the initial procedure
  - Was completed during a separate hospitalization from the initial procedure
- 3. The patient followed all physician instructions after the initial procedure

Did patient's situation meet warranty criteria shown above?

Yes, all of the above apply

