# SI-BONE® Complaint - Revision - Post Market - Feedback Reporting

Use this form to submit information about a complaint related to an SI-BONE product to Quality Affairs. Contact <u>QA@si-bone.com</u> if you have any questions.

Select the type of problem you are reporting

Problem with individual device or individual patient

#### **General Feedback about SI-BONE Product**

This is only for non complaint information. Examples: surgeon suggestions, meeting discussions, etc. For complaints, go back and select "Problem..."

### **Contact Info**

Use this to record your attempts to contact and gather information from the surgeon.

Your name	Sven Gueldener
Your email	sven.gueldener@si-bone.com
Your phone number	(491) 728-6091
Surgeon's name	Miguel Carvalho
Contact #1: How did you attempt to contact the surgeon?	Phone
Was this attempt successful?	Yes

#### **Complaint Overview**

Enter information about surgery that resulted in a problem with any SI-BONE implant, instrument or accessory (e.g., drill bit, pin).

Date you first heard of problem with SI-BONE product.	Thursday, July 20, 2023
Which device(s) was/were affected?	Instrument
Part number(s), if available	
500402	

Lot number(s), if available 321991

## **Product Complaint or Adverse Event?**

Decide what type of report you are submitting.

Use this form to submit information about a complaint related to an SI-BONE product to Quality Affairs. Contact <u>QA@si-bone.com</u> if you have any questions.

What is the nature of the problem you are reporting?

Product complaint without a patient problem. (Example: instrument breakage, no impact on patient.)

# **Product Complaint Without Adverse Event**

Use this form to report an SI-BONE product problem that was NOT associated with a patient adverse event.

Examples include:

- Damaged instrument
- Broken pin
- Bent pin
- Pin advancement but no patient injury
- Problem with packaging

If a damaged part injured a patient, go back and click on "Product complaint that caused or may have caused an adverse event."

Date part problem noticed	Tuesday, July 11, 2023
When was part problem detected?	Part damaged as a results of use
If part in question was used during procedure, was surgeon able to finish the procedure?	No, surgeon was unable to finish procedure with problem part
Was any part of product left in patient? Example: broken pin, metal shavings	Yes, a part was left in patient

#### Any further comments or information

During the explantation of an iFuse, the Tip of the Removal-Adapter broke and left inside the Implant. Dr. Carvalho was not able to remove the Implant (with the broken tip inside) and left it inside the Patient.

### Select Adverse Event Type

Select from the choices below. Your choice guides which section to complete.

If the first 3 do not apply, select "Other".

If a product problem occurred that did NOT cause a patient problem, go back and complete the "Product Complaint Without Adverse Event" section.

### **Symptomatic Implant Malposition Form**

Use this form if patient experienced symptomatic implant malposition resulting in nerve irritation.

(Information should be from SI-BONE staff who attended initial surgery) The surgeon completed all steps in the IFU, including:

- Patient setup (table, spine neutral position, prone or supine position)
- Inspection of instruments and implants prior to use
- Proper views (lateral, inlet and outlet) obtained during use of instruments and placement of implants that clearly showed recommended anatomic landmarks



- Appropriate implant starting position
- (If performed) proper use of neuromonitoring guide pin and equipment Use of length gauge for implant length selection
- Were standard wound closure techniques used?

For above question, be specific and include all steps of the revision surgery and any complications.

- Was the implant adjusted, removed or added?
- Were the explant holes filled with bone graft?
- Were osteotomes and the/or the removal adapter used?
- Was any non-iFuse hardware installed?

## Pain Did Not Improve or Recurred

#### Use this form if pain did not improve OR pain improved but then recurred

(Information should be from SI-BONE staff who attended initial surgery)

The surgeon completed all steps in the IFU, including:

- Patient setup (table, spine neutral position, prone or supine position)
- Inspection of instruments and implants prior to use
- Proper views (lateral, inlet and outlet) obtained during use of instruments and placement of implants that clearly showed recommended anatomic landmarks
- Appropriate implant starting position
- (If performed) proper use of neuromonitoring guide pin and equipment Use of length gauge for implant length selection
- Were standard wound closure techniques used?

### **Surgical Wound Problem**

Use this form if patient developed postoperative surgical wound problem (infection, dehiscence).

### **Other Problem**

Use this section ONLY if the patient problem is NOT:

- Implant malposition causing nerve irritation
- Pain did not improve or recurred
- Surgical wound problem

#### **Potential Warranty Case**

Please help evaluate whether this case could qualify for SI-BONE's warranty policy.

Did patient's situation meet all of the following?

Did patient undergo a revision procedure that met all of the following:

- 1. The initial procedure involved placement of 3 SI-BONE implants on the affected side
- 2. The revision procedure:
  - Was completed within 1 year of the initial procedure
  - Was completed at the same hospital or within the same hospital system as the initial procedure
  - Was completed during a separate hospitalization from the initial procedure
- 3. The patient followed all physician instructions after the initial procedure

# Did patient's situation meet warranty criteria shown above?

No, not all of the above apply

#### **Comment on warranty**

Need to get more informations from our Distributor. Surgeon and responsible Sales Rep are on holiday at the moment.